



THE SOUTH INDIA TEXTILE RESEARCH ASSOCIATION

SITRA TEXTILE TESTING AND SERVICE CENTRE

Dyers Association of Tirupur Building, D.No. 7/4, 2nd Floor, Pethichettipuram, 2nd Street, Rayapuram Main Road, Tirupur - 641 601

Ph: (0421) 4530443

E-mail : tprchem@sitra.org.in

Website: <http://www.sitra.org.in>

Address all correspondence to the Director, SITRA, 13/37, Avinashi Road, Coimbatore - 641014

Test Report No : V2400994

MARCH WORK PVT LTD.,

Report Date : 25-02-2025

Ref : 14/2/2025

Sample No : **V2400994-1**

Sample Description : SAMPLE NO: 01 March Supima Crew

Pilling Resistance [After Washing]	
<i>As per ISO 12945-1:2000(E)</i>	
Parameter(s)	
Pilling Resistance after Washing	4

Colour Fastness to Washing : Test 3	
<i>IS/ISO 105 - C10:2006 (RA 2021) C(3)</i>	
Parameter(s)	
Change in Colour	4
Staining on Triacetate	4-5
Staining on Cotton	4-5
Staining on Nylon	4-5
Staining on Polyester	4-5
Staining on Acrylic	4-5
Staining on Viscose	4-5

Degree of Pilling 1.Very severe pilling, 2.Severe pilling, 3.Moderate pilling, 4.Slight pilling, 5.No pilling. H -Denotes Hairiness,+ Indicate to Growth - Indicate to Shrinkage

Thumble Dryer,Note;

Change in Colour

1.Much Changed,2.Considerably Changed,3.Noticeble Changed,4.Slightly Changed,5.No change.

Staining

1.Much Stained,2.Considerably Stained,3.Noticeble Stained,4.Slightly Stained,5.No Stain.

Authorised by

(Krishnan.A)

-- End of the Report for the Sample no : V2400994-1 --
This is a computer generated report, hence does not require signature.



THE SOUTH INDIA TEXTILE RESEARCH ASSOCIATION
SITRA TEXTILE TESTING AND SERVICE CENTRE

Dyers Association of Tirupur Building, D.No. 7/4, 2nd Floor, Pethichettipuram, 2nd Street, Rayapuram Main Road, Tirupur - 641 601

Ph: (0421) 4530443

E-mail : tprchem@sitra.org.in

Website: http://www.sitra.org.in

Address all correspondence to the Director, SITRA, 13/37, Avinashi Road, Coimbatore - 641014

Test Report No : V2400994

MARCH WORK PVT LTD.,

Report Date : 25-02-2025

Ref : 14/2/2025

Sample No : **V2400994-2**

Sample Description : SAMPLE NO: 02 March Cotton Crew

Pilling Resistance [After Washing]	
<i>As per ISO 12945-1:2000(E)</i>	
Parameter(s)	
Pilling Resistance after Washing	4

Colour Fastness to Washing : Test 3	
<i>IS/ISO 105 - C10:2006 (RA 2021) C(3)</i>	
Parameter(s)	
Change in Colour	4
Staining on Triacetate	4-5
Staining on Cotton	4-5
Staining on Nylon	4-5
Staining on Polyester	4-5
Staining on Acrylic	4-5
Staining on Viscose	4-5

Degree of Pilling 1.Very severe pilling, 2.Severe pilling, 3.Moderate pilling, 4.Slight pilling, 5.No pilling. H -Denotes Hairiness,+ Indicate to Growth - Indicate to Shrinkage

Thumble Dryer,Note;

Change in Colour

1.Much Changed,2.Considerably Changed,3.Noticeble Changed,4.Slightly Changed,5.No change.

Staining

1.Much Stained,2.Considerably Stained,3.Noticeble Stained,4.Slightly Stained,5.No Stain.

Authorised by

(Krishnan.A)

-- End of the Report for the Sample no : V2400994-2 --
This is a computer generated report, hence does not require signature.